



## TĚSNĚNÍ

---

### Obsah

Těsnění ocelové s gumičkou .....	2
Těsnění měděné .....	2

## Těsnění ocelové s gumičkou



Označení	Pro závit
UR 1/8"	G 1/8"
UR 1/4"	G 1/4"
UR 3/8"	G 3/8"
UR 1/2"	G 1/2"
UR 3/4"	G 3/4"
UR 1"	G 1"
UR 1 1/4"	G 1 1/4"
UR 1 1/2"	G 1 1/2"
UR 2"	G 2"

## Těsnění měděné



Označení	Rozměr [mm]
Cu 6x10	6x10
Cu 8x12	8x12
Cu 8x14	8x14
Cu 10x14	10x14
Cu 10x16	10x16
Cu 12x16	12x16
Cu 12x18	12x18
Cu 14x18	14x18
Cu 14x20	14x20
Cu 16x22	16x22
Cu 18x24	18x24
Cu 20x26	20x26
Cu 22x27	22x27
Cu 24x30	24x30
Cu 26x32	26x32
Cu 28x34	28x34
Cu 30x36	30x36
Cu 32x38	32x38